

TITLE: Software Log

MODEL: Bolero

DATE: 2025-06-10

Reason for sending you this information

For our Bolero machine we have the following updates of the software.
The updates for the Bolero are available by type and can be downloaded from our website.

HMI firmware		HMI firmware		HMI firmware	
Item no:	002.071.015	Item no:	002.071.015	Item no:	002.071.015
Type:	All	Type:	All	Type:	All
2025-05-28	2.3.0	2023-01-02	2.0.5	2022-03-15	2.0.0
2024-08-23	2.2.2	2022-08-31	2.0.3	2021-10-15	1.2.3
2024-06-13	2.2.1	2022-04-19	2.0.2		
2023-05-05	2.1.0	2022-04-01	2.0.1		

HMI firmware version 2.3.0 (28-5-2025)

- Add start dose button on machines with cup detection to force start beverage
- Several bugs fixed

The first serial number produced with this update: **10046245**

HMI firmware version 2.2.2 (23-8-2024)

- Fixed timing issue payment system
- Fixed unintended error 3 and 5

The first serial number produced with this update: **020002520541**

HMI firmware version 2.2.1 (13-06-2024)

- Added support for various payment systems
- Added cup detection functionality for all models
- Added hide credit option
- Added max credit 9999
- Added correct feed-forward implementation for all models
- Fixed unintended errors, see SI240612-B
- Cosmetic improvements, larger icons, no animations, checkboxes

The first serial number produced with this update: **020002478112**

HMI firmware version 2.1.0 (05-05-2023)

- Optimized 3kW boiler control loop, added feed forward control (only 3KW machines)
- Added beverage strength management

The first serial number produced with this update: **020002389625**

HMI firmware version 2.0.5 (02-01-2023)

- Fix large menu button on 7 inch touchscreen being too sensitive

The first serial number produced with this update: **020002353011**

HMI firmware version 2.0.3 (31-08-2022)

- bug fixed realtime-vends (EVA-DTS)

The first serial number produced with this update: **020002320200**

HMI firmware version 2.0.2 (19-04-2022)

- bug fixed in the procedure of the 'screensaver management'
- backlight frequency changed to solve black screen at lower brightness for eco mode (only visible on Bolero 32, 33 and 43)
- bug fixed in the operation of the + and - buttons

The first serial number produced with this update: **020002289855**

HMI firmware version 2.0.1 (01-04-2022)

- fixed free vend beverages being erroneously counted as paid beverages in EVA-DTS report
- restored showing the serial number on the startup screen
- minor fixes in Polish translation

The first serial number produced with this update: **020002288007**

HMI firmware version 2.0.0 (15-03-2022)

- recipe builder / delete recipe / back to default recipe
- personalization, change icons and names of recipes and ingredients
- payment devices can now be used and configured
- select the default volume and default strength
- store a machine's configuration as the factory default on export and import
- reset machine counters
- several bugs fixed

The first serial number produced with this update: **020002282759**

HMI firmware version 1.2.3 (15-10-2021)

- fix touchscreen sensitivity on large buttons
- fix vertical alignment beverage selection screens
- EVA-DTS additions
- add PNG support
- Danish language added
- several bugs fixed