

TITLE : Software Log

MODEL: Sprso

DATE : 2025-06-24

Reason for sending you this information

For our Sprso machine we have the following updates of the software.

The updates for the Sprso are available by type and can be downloaded from our website.

	HMI firmware			Setting file		
	002.105.016 (STD)	002.105.021 (UK)	002.105.022 (NA)	002.104.039 (STD)	002.104.042 (UK)	002.104.043 (NA)
2025-06-18	01.02.10	1.05.11	-	1.02.03	1.05.02	-
2025-01-21	-	-	1.02.11	-	-	1.06.13
2024-05-15	1.02.09	1.05.09	-	1.02.03	1.05.02	-
2023-09-29	-	-	1.02.10	-	-	1.06.13
2023-03-17	1.02.05	1.05.05	1.02.06	1.02.02	1.05.01	1.06.12
2022-06-13	1.02.05	1.05.05	-	1.02.01	1.05.00	-

Software package version 2.09 (18-06-2025)

- bug fixed, Coffee valve closed during "Clean Coffee System (with pill)", which leads to unsatisfactory flow.

The first serial number produced with this update: **10022207**

!ONLY for the North American version!

Software package version 2.08 (17-01-2025)

- bug fixed, Coffee valve closed during "Clean Coffee System (with pill)", which leads to unsatisfactory flow.

The first serial number produced with this update: **020002539841**

Software package version 2.07 (29-05-2024)

- adjustment of the Circo brewer pressure force
- solving several small bugs

The first serial number produced with this update:

- **UK 020002378596**
- **STD 020002462148**

!ONLY for the North American version!

Software package version 2.06 (29-09-2023)

- bug fixed, sudden restarts

The first serial number produced with this update: **020002409920**

Software package version 2.05 (17-03-2023)

- flushing prior to standby function removed

The first serial number produced with this update: **020002381679**

TITLE : Software Log

MODEL: Sprso

DATE : 2025-06-24

Reason for sending you this information

For our Sprso machine we have the following updates of the software.

The updates for the Sprso are available by type and can be downloaded from our website.

Software package version 2.04 (13-06-2022)

- choice to select an internal / external water filter
- addition of the Ukrainian language
- some adjusted translations
- description error 00201 changed: *no water flow detected*
- solving several small bugs

The first serial number produced with this update: **020002287821**
