

# Service Information

**TITLE** : New manual resettable microswitch on steam boiler pressure switch

**MODEL** : FreshMilk

**DATE** : 2023-03-22

**NUMBER** : SI 230322

---

## Reason for sending you this information


Due to problems with the availability of the microswitch on the steam boiler pressure switch, the manually resettable microswitch was changed.

## Part information:

The manual resettable switch of the new micro switch has a different position, see the below picture for the new position.


The first machine with the new micro switch has serial number **020002379063**.

**Old**



press the button, at the bottom,  
down to reset

**New**



press the button, at the top, to  
reset

The microswitch is **integrated** in the steam boiler pressure switch and the complete steam boiler therefore it **cannot** be ordered separately.

## New Spare Part:

- none

## Deleted Spare Part:

- none