

Service Information

Title : Non applicable information (service part number) on the type plate
Model : Bolero 11, Bolero 21, Bolero 32, Bolero 43
Date : 07-06-2021

Reason for sending you this information

Non applicable information on the type plate of the instant machines.

Cause:

Due to an error, the service number 6.002.063.002 is mentioned on the type plate which is not suitable for the mentioned machines.

Solution:

From serial number **020002212766** or higher this service number is removed from the type plate as a service number is not needed on the type plate for these machines.

Part information:

Not applicable

New spare part:

Not applicable

Deleted spare part:

Not applicable

